



**TECH BULLETIN:  
H5705 FORD CALIPER  
SERVICE KIT**

**AFFECTED MODELS:** Ford Truck: 2009-2006 Explorer Sport Track, Explorer  
Mercury: 2009-2006 Mountaineer  
(Ref. F.M.S.I. Pads: D1109)

**ISSUE**

Some of these listed vehicles may produce a rattle noise over bumps from the rear of the vehicle.

**CAUSE**

This noise condition is the result of the rear brake calipers that do not incorporate an anti-rattle clip.

**SOLUTION**

USE CARLSON'S NEW SERVICE KIT H5705. Install our new brake caliper service kit to both sides of the vehicle, replacing the lower rail clip with a new rail clip that has a built in anti-rattle loop. Just follow the easy instructions contained in each kit.

*Because a brake job is more than just pads and shoes.*

