



**TECH BULLETIN:
H5668Q DODGE CALIPER
SERVICE KIT**

**AFFECTED MODELS: Dodge Vehicles (08-01) with Pad Set Numbers:
D655, D702, D966
(Ref. F.M.S.I. Pads: D702)**

SUBJECT

This Brake System uses Caliper Abutment Clips to ensure proper braking.



ISSUE

Caliper Abutment Clips can lose significant tension due to the heating and cooling during normal brake use. Corrosion can also degrade these clips. These factors can affect proper braking and cause uneven pad wear, resulting in a brake squeal and premature pad wear. Rubber bushings on this system can also become cracked or split over time.

SOLUTION

Install a new Brake Hardware Kit that includes new Caliper Abutment Clips and rubber bushings to ensure that all the parts in the brake system are working correctly.

Because a brake job is more than just pads and shoes.

