



**TECH BULLETIN:
H5616 FORD & LINCOLN
CALIPER SERVICE KIT**

**AFFECTED MODELS: Ford & Lincoln Vehicles (02-94) with Pad Set Numbers: D598
(Ref. F.M.S.I. Pads: D598)**

SUBJECT

This caliper design uses Pad Retaining Clips for optimal clearance and proper braking, along with rubber bushings to protect key components from dirt and grime.

Because a brake job is more than just pads and shoes.

ISSUE

Pad Retaining Clips can lose significant tension due to the heating and cooling during normal brake use. Corrosion can also degrade the performance. These factors can affect proper braking and cause uneven pad wear, resulting in a brake squeal and reduce the life of the pad. The rubber pin bushings can also become cracked or split over time, causing dirt and grime to enter the system.

SOLUTION

Install a new Brake Hardware Kit that includes new Pad Retaining Clips and rubber bushings to ensure that all the parts in the brake system are working correctly.

