



**TECH BULLETIN:  
H5751Q FORD  
CALIPER SERVICE KIT**

**AFFECTED MODELS: Ford Trucks (08-04) with Pad Set Numbers:  
D1012  
(Ref. F.M.S.I. Pads: D1012)**

**SUBJECT**

This caliper design utilizes Pad Locating Rail Clips for optimal function and proper braking, along with rubber bushings to protect key components from dirt and grime.

**ISSUE**

Pad Locating Rail Clips can lose significant tension and lose its form due to the heating and cooling during normal brake use. Corrosion can also degrade the performance. These factors can affect proper braking and cause uneven pad wear, resulting in a brake squeal and reduce the life of the pad. The rubber pin bushings can also become cracked or split over time, causing dirt and grime to enter the system.

**SOLUTION**

Install a new Brake Hardware Kit that includes new Pad Locating Rail Clips and rubber bushings to ensure that all the parts in the brake system are working correctly.

*Because a brake job is more than just pads and shoes.*

